


Icon Site Entrance – Underpass Lighting.

This map shows the location of the dark underpass under the Icon site entrance.

The lighting in this underpass appears to NOT be maintained by HCC – there are no yellow markers on their online fault reporting map as seen for the underpass under Lytton Way itself.



The photo below taken in daylight shows the lighting units that are not currently in use. It also shows the void on one side which is in complete darkness at night – as seen in the other picture where the reflective image laid out on the concrete slope is lit by torchlight.



The photo below is typical of all the OTHER underpasses seen across Stevenage on the rest of the cycleway network. It is well lit with lights coming on at twilight as seen here. Lighting is maintained by HCC – all lamps on all other underpasses are indicated on their fault reporting map – relevant extract shown below.

